

Bridge Inventory & Structural Recommendation Report For Roadway Concrete Pavement Rehabilitation Project I-15, MP 211-222

Structures

1F & 3F-454, I-15 NB/SB over Deer Crossing 1F & 3F-433, I-15 NB/SB over County Road 1F & 3F-453, I-15 NB/SB over County Road 1F & 3F-437, I-15 NB/SB over County Road 1F & 3F-434, I-15 NB/SB over County Road





Region: 3	Project Manager: John Higgins
Pin: 6576	Project Number: F-I-15-5(39)211
FiNet Number: 5259601D	Fiscal Year: 2011

Prepared by/Date: Tyson Schultz & Cody Buzianis /March 26, 2008

Signature, Director of Bridge Design:

Stan Burns

Signature, Director of Bridge Operations:

Rukhsana Lindsey

Table of Contents

Scope of Project:

- 1. Purpose of Concept Report
- 2. Project Information
- 3. Deficiencies & History
- 4. Plan
- 5. Work items to be completed
- 6. Work items to be deferred
- 7. Design Exceptions
- 8. Maintenance Considerations
- 9. Construction Considerations
- 10. Risk Analysis
- 11. Development Process

Schedule of Project:

- 1. Design Phase
- 2. Advertisement Date
- 3. Begin Construction
- 4. Complete Construction

Budget of Project:

- 1. Funding Source
- 2. Amount Programmed
- 3. Cost Estimate

REPORT SUMMARY

Scope of Project:

1. Purpose of Report

This report presents a conceptual overview of a project to perform Concrete Pavement Rehabilitation treatments for Bridges on I-15. It is intended to convey the need, scope, schedule, budget, and quality control process for the project.

2. Project Information

Region: 3 Route No.: I-15 Date: March 2008

Project Name: <u>I-15; MP 211-222</u>

R.P.: 211-222

Project Number: <u>F-I15-5(39)211</u> **PIN:** <u>6576</u>

FiNet: <u>5299601D</u>

Project Design: Bridge: UDOT Structures Division; Region 3

Project Mgr: John Higgins

3. Deficiencies & History: (Summarized from Project Inventory Report):

The 2007 inspection report indicates the following:

Bridge	Year Built	Sufficiency Rating	Deck	Super	Sub	Construction History		
1F-454	1984	97.7	7	8	7	None 1989-2007		
3F-454	1984	97.7	7	8	7	None 1989-2007		
3F-433	1984	93.7	6	7	7	None 1989-2007		
1F-433	1984	93.7	6	7	7	None 1989-2007		
3F-453	1984	93.7	7	7	7	None 1989-2007		
1F-453	1984	93.7	7	7	7	None 1989-2007		
1F-437	1984	93.7	7	7	7	None 1989-2007		
3F-437	1984	93.7	7	7	7	None 1989-2007		
3F-434	1984	93.7	7	7	7	None 1989-2007		
1F-434	1984	93.7	7	7	7	None 1989-2007		

Deficiencies (includes but are not limited to):

Structure All listed above on I-15 MP211-222

As of the Latest Inspection Report (11/8/2007):

- Deck & Approach Slabs have minor cracking with efflorescence with few visible shallow potholes.
- Parapet have minor scaling with no spalling or rebar exposed.

4. Plan:

This project is intended to provide "rehabilitation treatments" to extend the bridge life. By adding a healer sealer to the bridge decks and approach slabs. Then perform pothole patching and seal the parapets.

5. Work items to be completed:

This project will include the following items

- Apply healer sealer on the decks and approach slabs
- Perform pothole patching
- Waterproofing Membrane
- 2" HMA overlay
- 1" OGSC overlay
- Parapet sealing

6. Work items to be deferred:

This project won't include the following items:

• Roadway and safety items beyond what is related to the bridge repairs will not be included.

7. Design Exceptions:

No Design Exceptions are expected.

8. Maintenance Considerations:

Include Region 3 Maintenance Station 3422 in the concept development.

9. Construction Considerations:

The healer/sealer should be applied during temperatures ranging between 60°F to 80°F. If it is at all possible avoid hot summers when cracks are tight.

10. Risk Analysis:

Not Anticipated.

11. Development Process:

New or Major Reconstruction	
Rehabilitation	X
Preservation	

Schedule of Project:

Schedule meets roadway project deadline.

Budget of Project:


Funding Source: Federal Fund
CAA \$23,000,000
Cost Estimate: \$410,480

I-15 MP 211-222						
ITEM	QUANTITY	UNIT	UNIT COST		TOTAL COST	
Structures		-				
o tractar co						
1F & 3F-454						
Healer/Sealer Deck/Approach Slabs	9010	SF	\$	2.00	\$	18,020.00
Pothole Patching (up to 2%)	180	SF	\$	20.00	\$	3,600.00
Waterproof Membrane	9010	SF	\$	2.00	\$	18,020.00
3" Overlay (2" HMA & 1" OGSC)	169	TONS	\$	120.00	\$	20,272.50
Parapet Sealing	441	LF	\$	5.00	\$	2,205.00
1F & 3F-433			Ť	0.00	_	_,,,,
Healer/Sealer Deck/Approach Slabs	7881	SF	\$	2.00	\$	15,762.00
Pothole Patching (up to 2%)	155	SF	\$	20.00	\$	3,100.00
Waterproof Membrane	7881	SF	\$	2.00	\$	15,762.00
3" Overlay (2" HMA & 1" OGSC)	148	TONS	\$	120.00	\$	17,732.25
Parapet Sealing	386	LF	\$	5.00	\$	1,930.00
1F & 3F-453			Ť		Ė	.,, = 0.00
Healer/Sealer Deck/Approach Slabs	7982	SF	\$	2.00	\$	15,964.00
Pothole Patching (up to 2%)	160	SF	\$	20.00	\$	3,200.00
Waterproof Membrane	7982	SF	\$	2.00	\$	15,964.00
3" Overlay (2" HMA & 1" OGSC)	150	TONS	\$	120.00	\$	17,959.50
Parapet Sealing	390	LF	\$	5.00	\$	1,950.00
1F & 3F-437			Ť		_	-,,
Healer/Sealer Deck/Approach Slabs	8412	SF	\$	2.00	\$	16,824.00
Pothole Patching (up to 2%)	168	SF	\$	20.00	\$	3,360.00
Waterproof Membrane	8412	SF	\$	2.00	\$	16,824.00
3" Overlay (2" HMA & 1" OGSC)	158	TONS	\$	120.00	\$	18,927.00
Parapet Sealing	412	LF	\$	5.00	\$	2,060.00
1F & 3F-434			Ť	0.00	Ψ	2,000.00
Healer/Sealer Deck/Approach Slabs	9862	SF	\$	2.00	\$	19,724.00
Pothole Patching (up to 2%)	198	SF	\$	20.00	\$	3,960.00
Waterproof Membrane	9862	SF	\$	2.00	\$	19,724.00
3" Overlay (2" HMA & 1" OGSC)	185	TONS	\$	120.00	\$	22,189.50
Parapet Sealing	483	LF	\$	5.00	\$	2,415.00
- anapor coaming	.00		Ť	0.00	Ψ	2,.10.00
Subtotal			1		\$	297,448.75
					Ψ	257,140.72
Traffic Control					Incl	uded in Roadway
Mobilization					Included in Roadway	
Public Information Service					Included in Roadway	
Roadway Tie In (150-feet on each end of bridge)					Included in Roadway	
			1			
Subtotal			1		\$	297,448.75
			 		┪	2.,
PE/CE 18%			 		\$	53,540.78
Contigency 20%					\$	59,489.75
conagency 2070					Ψ	57,707.73
Project Total					\$	410,479.28
1 10jeul 10tai			<u> </u>		Ψ	+10,4/3.20

Location Map

I-15, MP 211-222





S:\STR\Concept Reports\Completed Concept Reports\Other FY 2011\I-15 Milepost 211-222\I-15 MP 211-222 Concept Report.doc

